


STRAIGHT JACK




FOR FLEXIBLE CABLE

MODEL	3091-1-*	3091-2-*	3091-3-*	3091-4-*	3091-5-*
CABLE	RG55, 142, 223, 400	RG58, 141, 303	RG174, 179, 187, 188, 316	RG180, 195	RG178, 196
a =	.830	.830	.700	.800	.800
NOTES	crimp or solder	crimp or solder	crimp or solder	crimp or solder	crimp or solder

NOTE: For crimp version (passivated only) add suffix "C"


STRAIGHT JACK



FOR FLEXIBLE CABLE

MODEL	3602-1-*	3602-2-*	3602-3-*	3602-4-*	3602-5-*
CABLE	RG55, 142, 223, 400	RG58, 141, 303	RG174, 179, 187, 188, 316	RG180, 195	RG178, 196
NOTES	crimp/clamp	crimp/clamp	crimp/clamp	crimp/clamp	crimp/clamp


FLANGE MOUNT JACK



FOR FLEXIBLE CABLE

MODEL	3146-1-1	3146-2-1	3146-3-1
FLANGE	4 hole	4 hole	4 hole
CABLE	RG55, 142, 223, 400	RG58, 141, 303	RG174, 179, 187, 188, 316
NOTES	crimp or solder	crimp or solder	crimp or solder

BULKHEAD JACK



FOR FLEXIBLE CABLE

MODEL	3905-1-*	3905-2-*	3905-3-*	3905-4-*	3905-5-*	3905-29-*
CABLE	RG55, 142, 223, 400	RG58, 141, 303	RG174, 179, 187, 188, 316	RG180, 195	RG178, 196	RG174DS, RG188DS, RG316DS
a =	.220	.220	.115	.160	.085	.140
NOTES	wedge clamp	wedge clamp	wedge clamp	wedge clamp	wedge clamp	wedge clamp

*-1 indicates gold plated stainless steel all over.

-9 indicates passivated (stainless finish) except in areas where gold plating is required for solderability.